



Work Order (Bid Form)

Auditor: Scott Haislip (615) 274-2565 or (615) 424-2565

WORK ORDER INFORMATION

Work Order Name: WO/10010MC1893/1

Work Order Type: Weatherization

Audit Name: 10010MC1893

CLIENT INFORMATION

Client Name:

Address:

Client ID: 10010MC1893

LAVERGNE, TN 37086

Alt. Client ID:

AGENCY INFORMATION

Agency: Mid-Cumberland Community Action Agency

Agency Phone: (615) 742-1113

Address: P.O.Box 310, 233 Legend Drive, Suite 103
Lebanon, TN 37088-0310

Fax:

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

SITE BUILT 2005 ON SLAB
2,263 SQ FT
2 HEATING UNITS ARE LOCATED IN ATTIC
16 WINDOWS
2 DOORS

Client Name:

Client ID: 10010MC1893

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/10010MC1893/1

Report Run On: 5/17/2010

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 6

Measures

Measure 1 SEAL PLUMBING PENETRATIONS UNDER KITCHEN SINK

Components

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Other	AIR SEALING	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 SEAL PLUMBING PENETRATIONS UNDER BATHROOM VANITY & COMMODE SUPPLY LINE (3)

Components

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Other	AIR SEALING	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 10010MC1893

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/10010MC1893/1

Report Run On: 5/17/2010

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 6

**Measure 3 ADD DOOR SWEEP TO FRONT, BACK,
& KITCHEN DOOR LEADING TO
GARAGE****Components****Inspected****Comment**

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Doors	DOOR SWEEP	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 4 CAULK AROUND LIVING ROOM
WINDOW FROM INTERIOR****Components****Inspected****Comment**

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Windows	AIR SEALING	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 10010MC1893

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/10010MC1893/1

Report Run On: 5/17/2010

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 6

Measure 5 INSTALL ENERGY LID TO ATTIC PULL
DOWN STAIRS**Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Insulation	ENERGY LID	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 6** Attic Ins. R-19**Components** A1**Inspected****Comment** CONTRACTOR TO VERIFY☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-19	SqFt	1176					
Other Detail									
Measure Sub Total:							Sub Total:		

Field Notes:

Client Name:

Client ID: 10010MC1893

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/10010MC1893/1

Report Run On: 5/17/2010

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 6

Measure 7 INSTALL STORM DOORS TO FRONT & BACK DOORS**Components****Inspected****Comment** 36" X 80"
32" X 80"☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Doors	STORM DOORS	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 8 MASTIC SEAL DUCT SYSTEM & RETURN AS NEEDED; PAN READING 0.7-2.1****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Heating Equipmen	MASTIC SEAL	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:Client Name:
Client ID: 10010MC1893
Alt. Client ID:**Work Order (Bid Form)**
Work Order Name: WO/10010MC1893/1
Report Run On: 5/17/2010DOE Weatherization Assistant
Version 8.6.0
Page 5 of 6

Measure 9 INSTALL AIR FILTER & LEAVE 5 FOR HOMEOWNER**Components****Inspected****Comment** 20" X 25" & 14" X 30"☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Heating Equipmen	AIR FILTERS	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 10 DWH Tank Insulation****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 10010MC1893

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/10010MC1893/1

Report Run On: 5/17/2010

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 6